

F1G.1

| | |
|-------|--------|
| X.X | +0.1 |
| X.XX | +0.01 |
| X.XXX | +0.001 |
| ANG. | +0.5 |





FIG. 2



X.X + -0.1
X.XX + -0.01
X.XXX + -0.001
ANG. + -0.5




FIG. 3

X.X + - 0.1
X.XX + - 0.01
X.XXX + - 0.001
ANG. + - 0.5






FIG. 4




F16.5

F16.6




F/6.7

40



+ - 0.1
X . XX + - 0.01
X . XXX + - 0.001
ANG. + - 0.5



F16.8

X.X +0.1
X.XX +0.01
X.XXX +0.001
ANG. +0.5

X.X + -0.1
X.XX + -0.01
X.XXX + -0.001
ANG. + -0.5

F16.9

